

Inspection Photos
Operator: Hilcorp Energy
API: 067-08640
Date: 6/1/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revgetation is progressing largely with western wheatgrass, smooth brome, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area comprised of gambel oak shrubland with Indian ricegrass, yucca, snakeweed, squirreltail, and *chaetopappa ericioides*.