

Inspection Photos
Operator: Simcoe
API: 471426
Date: 6/13/2022



Photo 1. View of the right of way (ROW) from access entrance facing eastward along ROW.



Photo 2. View of ROW in foreground facing northward. Desirable vegetation such as sand dropseed, crested wheatgrass, and smooth brome observed.




Photo 3. View of Russian knapweeds both treated and untreated observed along the pipeline ROW. Similar to surrounding pasture, Russian knapweeds partially appear treated and additional individuals remain. Continued management and treatment is needed.



Photos 4. View of area along the western portion of the pipeline ROW where hydromulch is observed and seeding appears to be conducted.



Photo 5. View of fencing repaired in the western portion of the pipeline ROW.




Photo 6. View of reference area comprised of open grass pasture with smooth brome, crested wheatgrass, and foxtail. Russian knapweeds infestation outside of ROW appears partially treated as living a treated individuals remain.