

Inspection Photos
Operator: Simcoe
API: 067-06686
Date: 6/13/2022



Photo 1. View of the project are from the well pad entrance facing center.



Photo 2. View of the eastern project area from the well pad entrance facing southward. Revegetation is progressing with crested wheatgrass, sand dropseed, and western wheatgrass.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area comprised of open grass field with smooth brome, crested wheatgrass, and western wheatgrass. As Russian knapweed is present here, continued vigilance and treatment within the project area is needed.