

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Stained soil / mechanical issue with wellhead valve, stained soil needs to be removed.

Corrective Action: Comply with COGCC housekeeping rules

Date: 07/13/2022

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: 4' barb wire around all equipment

Corrective Action:

Date:

Equipment:

corrective date

Type: Bird Protectors # 1

Comment:

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Vertical Separator # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: plumbed to surface

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: electric equipment

Corrective Action:

Date:

Type: Deadman # & Marked # 4

Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	According to COGCC data this well has produced oil and no gas since 3/1/2020. Venting / flaring issues may be present on this location. There is no gas measurment equipemtn on location.		
Corrective Action:	Comply with COGCC venting / flaring rules		Date: 06/14/2022

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 203449 Type: WELL API Number: 001-09008 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 12/30/2021 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 6/13/22 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Vetter 1-15A Company Name- Renegade API- 05-001-09008 In Adams County Colorado. While there, I observed SI well During this inspection the following possible compliance issues were observed: Stained soil / mechanical issue with wellhead valve, stained soil needs to be removed. Comply with COGCC housekeeping rules 7/13/22 According to COGCC data this well has produced oil and no gas since 3/1/2020. Venting / flaring issues may be present on this location. There is no gas measurement equipment on location. Comply with COGCC venting / flaring rules 6/14/22 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	06/14/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403080534	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5780571
699504025	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5780556