

Inspection Photos

API: 055-06316

Operator: OXY USA INC

Inspection Date: 6/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 6/16/2022

Inspection Photos



Photo 1. Facing south along the access road. There are some signs of erosion along the steep grade of the road. Stormwater should be diverted off the road to reduce erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 6/16/2022

Inspection Photos



Photo 3. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 6/16/2022

Inspection Photos



Photo 4. There was an audible gas leak. Gas monitor also detected a leak. Operator was notified by phone call of this issues.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 6/16/2022

Inspection Photos



Photo 5. There are noxious weeds at the southwest corner of the location.
Red arrow → Canada thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 6/16/2022