

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2022

Submitted Date:

06/23/2022

Document Number:

701103239

**FIELD INSPECTION FORM**Loc ID 313159 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10724

Name of Operator: NORTH SHORE EXPLORATION AND PRODUCTION

Address: 105 EDGEVIEW DR SUITE 400

City: BROOMFIELD State: CO Zip: 80021

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hindle, Holly		holly@northshoreenergyllc.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264680	WELL	SI	11/01/2019	GW	081-07102	EVANS FEDERAL 22-28	SI

**General Comment:**

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

- No API # on well sign.
- No API # on battery sign. No public road used to access the Tank battery site
- Metal tank by meter shed and separator NFPA, contents, and capacity are faded.
- Deadman marker south west of well has been bent over.
- Weeds growing inside of tank battery berm and separator berm and around well.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Metal tank by meter shed and separator NFPA, contents, and capacity are faded.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/31/2022
Type	WELLHEAD		
Comment:	No API # on well signs.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/31/2022
Type	BATTERY		
Comment:	No API # on battery sign. no public road used to access the Tank battery site;		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/31/2022

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds growing inside of tank battery berm and separator berm and around well.		
Corrective Action:	Comply with Rule 606 (housekeeping) Comply with Rule 610 (Fire Hazards)	Date:	07/09/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	#		
Comment:	Deadman marker south west of well has been bent over.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	07/09/2022
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	See housekeeping section. Weeds growing in berm.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Comment:		See housekeeping section. Weeds growing in berm.						
Corrective Action:							Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS			
PRODUCED WATER	1	400 BBLs	STEEL AST		,			
Comment:								
Corrective Action:							Date:	
<b>Paint</b>								
Condition	Adequate							
Other (Content)								
Other (Capacity)								
Other (Type)								
<b>Berms</b>								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Earth	Adequate	Walls Sufficient						
Comment:		See housekeeping section. Weeds growing in berm.						
Corrective Action:							Date:	
<b>Venting:</b>								
Yes/No	NO							
Comment:								
Corrective Action:							Date:	
<b>Flaring:</b>								
Type								
Comment:								
Corrective Action:							Date:	

**Inspected Facilities**Facility ID: 264680 Type: WELL API Number: 081-07102 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Form 4 Doc # 403056779

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flowline**

#1	Type: Sales Line	of Lines
----	------------------	----------

Flowline DescriptionFlowline Type: Sales Line Size: \_\_\_\_\_ Material: \_\_\_\_\_

Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_

Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. AbandonmentComment: Witness flowline test from well to meter. Held steady 345 psi for 30 mins

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103254	Inspection 701103239 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5787985">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5787985</a>