

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2022

Submitted Date:

06/23/2022

Document Number:

702500112

**FIELD INSPECTION FORM**

Loc ID 306966 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 17 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285561	WELL	PR	07/12/2006	CBM	067-09199	EMMETT WOLTER 2	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
<b>Lease Road:</b>			
Type	Main		
comment:	Gravel main road		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment associated with not in use flow line (IMG 05).		
Corrective Action:	Use or remove unused equipment per rule 606.		Date: <u>07/22/2022</u>
Type	UNUSED EQUIPMENT		
Comment:	9 unused hammer unions surrounding wellhead (IMG 03 and IMG 04).		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Location enclosed by barbed wire fencing.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Wellhead, separation equipment, gas meter run, and produced water tank enclosed by stock panel.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric prime mover.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 3	
Comment:	Telemetry, electric meter and panel, electric cabinet.	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Calibration record is up to date.	
Corrective Action:		Date:
Type: Flow Line	# 4	
Comment:	In use: 3" line from wellhead to separator, 2" line from separator to gas meter run, line from separator to produced water tank.  Not in use: 1/2" flow line on northwest corner of pump jack (IMG 05).	
Corrective Action:	If flow line is planned to be used again: apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)  If flow line is not planned to be used: complete flowline abandonment to comply with Rule 606.	Date: 07/19/2022
Type: Bird Protectors	# 1	
Comment:	Separator vent stack screened properly.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.259357,-107.617549
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	Produced water
Other (Capacity)	95 bbl
Other (Type)	Cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal secondary containment.			
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
------	--

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 285561 Type: WELL API Number: 067-09199 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Gravel	Pass					
Compaction	Pass					
Rip Rap	Pass					Rip rap run off on
		Compaction	Pass			

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**      NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500113	Photo Doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5787988">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5787988</a>