

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2022

Submitted Date:

06/23/2022

Document Number:

702500108

FIELD INSPECTION FORM

Loc ID 326212 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216049	WELL	PR	12/29/1990	CBM	067-07655	ISAAC TRUST A 1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Lease Road:			
Type	Access		
comment:	Gravel access road.		
Corrective Action:		Date:	

Overall Good:

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds beginning to encroach on northwest corner of location (IMG 03).		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Wellhead and separator enclosed by stock panel. Buried produced water tank is enclosed by steel pipe barricade fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location enclosed by wire fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 4		
Comment:	4" line from wellhead to separator, 3" line from separator to off location, 2 lines from separator to produced water tanks.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter run located in separator house. Calibration is up to date.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 3	
Comment:	Separator vent stack and above ground produced water tank are screened properly. Partially buried produced water tank mesh screen leaves ~2" gap that birds or bats could potentially enter (IMG 04).	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Bradenhead is accessible.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		37.256428,-107.601173
Comment:	Above ground produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	produced water
Other (Capacity)	300 bbl
Other (Type)	Cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Compacted dirt and gravel earth berm.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.256954,-107.600990
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Produced water
Other (Capacity)	95 bbl
Other (Type)	cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216049 Type: WELL API Number: 067-07655 Status: PR Insp. Status: PR

Producing Well

Comment: [Free flowing well.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass					
		Compaction	Pass			
Gravel	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500109	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5787986