

Inspection Photos

June 22, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 334873

Location Name: Savage-66S94W /35SWSW

Inspection Document #: 702800377

Garfield County, CO

SWSW Section 35 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Savage-66S94W /35SSWSW
Location ID: 334873



Photo 1. Photo taken from the west of the Location shows an overview of the western production area.



Photo 2. Photo taken from the west of the Location shows an overview of the eastern production area.

Inspection Photos
Location Name: Savage-66S94W /35SWSW
Location ID: 334873



Photo 3. Photo taken from the northwestern interim area of the Location shows a dense patch of bulbous bluegrass (List C Noxious).



Photo 4. Photo taken from the northern interim area of the Location shows a dense patch of jointed goatgrass (List B Noxious)

Inspection Photos
Location Name: Savage-66S94W /35SWSW
Location ID: 334873



Photo 5. Photo taken from the northern interim area of the Location, directly adjacent to the working pad area shows where revegetation has completely failed. Vegetation in the photo is field bindweed (List C Noxious).



Photo 6. Photo taken from the northern interim area of the Location, directly adjacent to the working pad area shows where revegetation has completely failed.

Inspection Photos
Location Name: Savage-66S94W /35SWSW
Location ID: 334873



Photo 7. Photo taken from the northern interim area of the Location shows sporadic cover of seeded native perennial grasses.



Photo 8. Photo taken from the south of the Location shows an area where seeding of native perennial grasses has been somewhat successful (blue circle), and a dense patch of jointed goatgrass, where seeding has failed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800377

Inspection Photos
Location Name: Savage-66S94W /35SWSW
Location ID: 334873



Photo 9. Photo taken from the northern production area shows an unmarked guy line anchor.

Inspection Photos
Location Name: Savage-66S94W /35SWSW
Location ID: 334873



Photo 10. Photo taken from the west of the Location shows where stormwater has broken through a stormwater diversion ditch and is degrading adjacent interim areas.



Photo 11. Refer to Photo 10 comment.