

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2022

Submitted Date:

06/20/2022

Document Number:

702500101

FIELD INSPECTION FORM

 Loc ID 326440 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
 OGCC Operator Number: 10679
 Name of Operator: LOGOS OPERATING LLC
 Address: 2010 AFTON PLACE
 City: FARMINGTON State: NM Zip: 87401
Contact Information:

Contact Name	Phone	Email	Comment
, General		regulatory@logosresourcesllc.com	All SW field inspections
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	All SW field Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216494	WELL	PR	07/01/2019	GW	067-08100	BONDAD 33-9 25A	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
Lease Road:			
Type	Access		
comment:	Gravel access road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:	Emergency contact number listed on well sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused metal tubing near separator (IMG 08).		
Corrective Action:	Use or remove unused equipment per rule 606.		Date: 07/03/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Wellhead enclosed by wire fencing. Produced water tank and separator enclosed by wire fencing.		
Corrective Action:			Date:
Equipment:			
Type: Flow Line	# 3		corrective date
Comment:	2" line from wellhead to separator, 2" line from separator to produced water tank, 2" line from produced separator to off location		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Rig anchors are less than 4' (IMG 04, IMG 05, IMG 06, IMG 07).		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 07/03/2022

Type: Bird Protectors	# 1		
Comment:	Horizontal heated separator vent stack screened properly.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV STEEL		37.122924,-107.843803
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	produced water
Other (Capacity)	125 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Berm height appears insufficient (IMG 09).			
Corrective Action:	Confirm secondary containment capacity is adequate. If not repair secondary containment devices per Rule 912.d.(1).			Date: 07/08/2022

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 216494 Type: WELL API Number: 067-08100 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Compaction	Pass			

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403083652	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5783451
702500102	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5783448