

| | | | | | | |
|-------------------|--|------------------|-----------------------|------------|-------------|-------|
| Today's Date: | 6/17/2022 | | | | | |
| Well Name: | HUBER-DOBBINS 1-31 | Location: | Sec: 31 | Twn: 035N | Rng: 008W | UL: J |
| API Number: | 05.067.07580 | Footage: | 1490' FSL & 2510' FEL | | | |
| Operator: | Hilcorp Energy Company | Area/Run/MSO: | 01 | 0100 | Austin Haws | |
| Meter #: | DR0481RS | | Pipeline: | HEC | | |
| | | | | | | |
| INC Number: | 702500094 | Agency: | COGCC | Inspector: | Alex Klink | |
| Type of INC: | Written | Photos Required: | Yes | Due Date: | 7/2/2022 | |
| Issue of Concern: | <div>Comment: 3 of 4 rig anchor markers not secured properly (IMG 03, IMG 04, IMG 05).</div> <div>Corrective Action: Install proper guy line markers per Rule 1003.a</div> | | | | | |

From: Ashton Hemphill <ahemphill@hilcorp.com>

Sent: Monday, June 27, 2022 5:01 AM

To: Tammy Jones <tajones@hilcorp.com>; Freddy Proctor <fproctor@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Shara De Velder <sdevelder@hilcorp.com>

Subject: RE: HUBER-DOBBINS 1-31 - INC - 702500094

All rig anchor markers are secured properly and old ones are disposed of.



