

Inspection Photos

June 16, 2022

Operator: Foundation Energy Management LLC - #10112
Quicksilver Resources Inc. - #10255

Location ID: 313334

Location Name: Donald-67N93W /11NWNE

Inspection Document #: 702800366

Moffat County, CO

NWNE Section 11 T7N R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Donald-67N93W /11NWNE
Location ID: 313334

6/16/22
+40.578085,-107.797151
223° SW



Photo 1. Photo taken from the east, at the Location entrance shows an overview of the southern portion of the Location. Photo also shows Scotch thistle, a List B Noxious Weed.

6/16/22
+40.578085,-107.797151
263° W



Photo 2. Photo taken from the east, at the Location entrance shows an overview of the northern portion of the Location. Photo also shows Scotch thistle, a List B Noxious Weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800366

Inspection Photos
Location Name: Donald-67N93W /11NWNE
Location ID: 313334



Photo 3. Photo taken from the east of the Location shows areas of the Location which do not appear to have been decompacted, and gravel from the pad surface remains. Vegetation establishment is sparse.



Inspection Photos
Location Name: Donald-67N93W /11NWNE
Location ID: 313334



Photo 4. Photo taken from the south of the Location shows an area where perennial plant establishment has failed and the vegetation community is dominated by undesirable plant species/annual weeds.



Photo 5. Photo taken from the southwest of the Location shows whitetop, a CO List B Noxious Weed.



Inspection Photos
Location Name: Donald-67N93W /11NWNE
Location ID: 313334



Photo 6. Photo taken from the west of the Location shows the Location has not been recontoured; the Location perimeter berm remains. Note also the power line (red arrow) associated with the Location which must be removed per Rule 1004.a.



Photo 7. Photo taken from the east of the Location shows a rip-rap lined stormwater outlet with a ditch and berm which must be removed and recontoured per Rule 1004.a.



Inspection Photos
Location Name: Donald-67N93W /11NWNE
Location ID: 313334



Photo 8. Photo taken from the northeast of the Location shows equipment which must be removed per Rule 1004.a.



Photo 9. Photo taken from the northeast of the Location shows off-Location equipment associated with the Location which must be removed per Rule 1004.a.



Inspection Photos
Location Name: Donald-67N93W /11NWNE
Location ID: 313334



Photo 10. Photo taken from the northeast of the Location shows equipment which must be removed per Rule 1004.a.



Photo 11. Refer to Photo 10 comment.



Inspection Photos
Location Name: Donald-67N93W /11NWNE
Location ID: 313334



Photo 12. Refer to Photo 10 comment.



Photo 13. Photo taken from the northeast of the Location shows a pile of rock which must be removed per Rule 1004.a.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800366

Inspection Photos

Location Name: Donald-67N93W /11NWNE

Location ID: 313334



Photo 14. Photo taken from the southeast of the Location shows a guy line anchor which must be removed per Rule 1004.a.



Photo 15. Photo taken from the center of the Location shows a compacted soil layer.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800366

Inspection Photos
Location Name: Donald-67N93W /11NWNE
Location ID: 313334



Photo 16. Photo taken from the south of the Location shows reference area vegetation is native rangeland.

