

Final Reclamation Inspection

May 10th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323096

Inspection Document #: 701900366

SESW Section 21 T3N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 1. 2021 aerial imagery of the well pad and tank battery. Note: well pad and tank battery shared a disturbance pad. Historical imagery confirms that the tank battery was on the southern end of the disturbance and has been completely absorbed by the new Kerr McGee production facility, location ID 464149.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 2. Overview photo of the well pad taken at ground level from the southern edge looking north.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 3. Cardinal overview photos of the well pad. Left photo facing north and right photo facing east.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 4. Cardinal overview photos of the well pad. Left photo facing south and right photo facing west. Note: well pad shows minimal perennial plant establishment for stormwater control. Large pile of gravel in southwest corner of well pad. (see photo 5).

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 5. gravel in southwest corner of well pad.