

Final Reclamation Inspection

May 25th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 322607

Inspection Document #: 701900401

SENW Section 13 T6N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: R. Anderson Unit 1-13
Location ID: 322607




Photo 1. 2021 aerial imagery of the well pad and tank battery.

Inspection Photos
Location Name: R. Anderson Unit 1-13
Location ID: 322607



Photo 2. Overview photo of the well pad taken at ground level from the southern edge looking north. Note: well pad falls within a pasture that is actively being grazed by cattle.

Inspection Photos
Location Name: R. Anderson Unit 1-13
Location ID: 322607



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: R. Anderson Unit 1-13
Location ID: 322607



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad has a lower density of the dominant grass species (salt grass) compared to the reference area. (see photo 5). Weedy kochia is present within the site.

Inspection Photos
Location Name: R. Anderson Unit 1-13
Location ID: 322607



Photo 5. well pad reference.

Inspection Photos
Location Name: R. Anderson Unit 1-13
Location ID: 322607



Photo 6. Overview photo of the tank battery taken at ground level from the eastern edge looking west. Note: the tank battery disturbance still remains and a variance form is in process.

Inspection Photos
Location Name: R. Anderson Unit 1-13
Location ID: 322607



Photo 7. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right facing east.

Inspection Photos
Location Name: R. Anderson Unit 1-13
Location ID: 322607



Photo 8. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right facing west.