

Location

| | | | |
|--------------------|-------------------------------------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | wellsite in a planted alfalfa field | | |
| Corrective ActionL | | | Date: |

Overall Good:

| | | | |
|----------------------|---|--|------------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | No WH sign | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | | Date: 09/22/2022 |

Emergency Contact Number:

| | | | |
|--------------------|--|--|-------------|
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| Spills: | | | | |
|----------------|------|--------|--|--|
| Type | Area | Volume | | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|----------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Ag panel | | |
| Corrective Action: | | | Date: |

| Equipment: | | | | corrective date |
|---------------------------|--------------------|--|--|-----------------|
| Type: Bradenhead | # 1 | | | |
| Comment: | exposed at surface | | | |
| Corrective Action: | | | | Date: |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | automation | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | |
|--------------------|----|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
| Type | | | |

| | | |
|--------------------|-------|--|
| Comment: | | |
| Corrective Action: | Date: | |

Inspected Facilities

Facility ID: 264907 Type: WELL API Number: 123-21125 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 03/21/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Wednesday 5-22-2022 at approximately 1220 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Oxy/Kerr McGee Location name: Harkis 1-15A API #05-123-21125 County: Weld Weather: Clear/overcast. Location: Dry. While there, I observed wellsite, SI at the time of inspection. During this inspection, I observed the following compliance issue: 605.d signs: No Sign at the WH, CA date 9-22-2022. See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p> | revasr | 06/22/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403087243 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5786592 |
| 702400623 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5786588 |