

Resolved Photos – DAVIS 2-5

05.067.08150

| | | | | | | |
|-------------------|---|------------------|-----------------------|------------|-------------|-------|
| Today's Date: | 6/17/2022 | | | | | |
| Well Name: | DAVIS 2-5 | Location: | Sec: 05 | Twn: 034N | Rng: 008W | UL: G |
| API Number: | 05.067.08150 | Footage: | 1670' FNL & 1414' FEL | | | |
| Operator: | Hilcorp Energy Company | Area/Run/MSO: | 01 | 0100 | Austin Haws | |
| Meter #: | DR0479RF | | Pipeline: | HEC | | |
| INC Number: | 702500087 | Agency: | COGCC | Inspector: | Alex Klink | |
| Type of INC: | Verbal | Photos Required: | Yes | Due Date: | 7/16/2022 | |
| Issue of Concern: | <p>Comment: Last gas meter calibration was 4/13/21 (IMG 05). Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).</p> <p>Comment: Unused stock panels near produced water tank (IMG 06). Corrective Action: Use or remove unused equipment per rule 606.</p> <p>Comment: Tarp near pump jack (IMG 04) and poly tubing near compressor house (IMG 09). Corrective Action: Remove trash to comply with rule 606.</p> <p>Comment: Not in use: 1" flow line uncapped near separator (IMG 08), 1" flow line uncapped near pump jack (IMG 03). Corrective Action: Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)</p> <p>Comment: 1 rig anchor with marker, 3 rig anchors with markers not secured properly (IMG 10, IMG 11, IMG 12). Corrective Action: Install proper guy line markers per Rule 1003.a</p> | | | | | |

Stock panels near produced water tank as shown in photo are put back up around the well head.





All the trash and unused parts have been picked up and have been disposed of properly.



The 1" flow line uncapped near separator, and near pump jack have been properly hooked up for emissions.







All rig anchor markers are secured properly.

