

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2022

Submitted Date:

06/29/2022

Document Number:

702500136

**FIELD INSPECTION FORM**

Loc ID 326093 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 20 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215854	WELL	PR	02/02/1991	CBM	067-07459	CARTER UTE 107	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Dirt access road is developing ruts.		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Above ground produced water tank signs beginning to deteriorate (IMG 10).		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment at wellhead (IMG 06). Unused equipment at southern separator (IMG 05).		
Corrective Action:	Use or remove unused equipment per rule 606.		Date: <u>07/13/2022</u>
Type	OTHER		
Comment:	Impacted material at oil container north of compressor skid (IMG 07). Impacted material west of partially buried produced water tank (IMG 08). Impacted materail west of compressor skid (IMG 09).		
Corrective Action:	Remove impacted material per rule 906 and 1002.f.		Date: <u>07/13/2022</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Produced water tanks are enclosed by wire fencing.		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Telemetry, cathodic protection, electric panel.		
Corrective Action:			Date:

Type: Prime Mover	# 1		
Comment:	Gas powered		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Other	# 3		
Comment:	Oil containers. 2 oil containers do not have spill prevention (IMG 03 and 04).		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.		Date: <u>07/13/2022</u>
Type: Compressor	# 1		
Comment:	Compressor skid with metal roof.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:	Above ground produced water tanks and both separator vent stacks are screened properly.		
Corrective Action:			Date:
Type: Flow Line	# 10		
Comment:	In use: 4" line from wellhead to separator, 1" line from separator to compressor skid, 3 1" lines to produced water tanks, 2" line from southern separator to partially buried produced water tank, 2" and 4" line at northern separator, 1" line at above ground produced water tanks.  Not in use: 2" line stubbed up near southern separator, with no lock out/tag out.		
Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)		Date: <u>07/13/2022</u>
Type: Gas Meter Run	# 1		
Comment:	Meter calibration is up to date.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.020918,-107.880493
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	120 bbl
Other (Type)	cone top

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		Gravel and dirt earth berm.				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	3	500 BBLs	STEEL AST		37.020577,-107.880284		
Comment:		3 above ground produced water tanks, each with 500 bbl capacity.				Date:	
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)	500 bbl						
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Gravel and dirt earth berm.				Date:	
Corrective Action:						Date:	
<b>Venting:</b>							
Yes/No							
Comment:							
Corrective Action:							
Date:							
<b>Flaring:</b>							
Type							
Comment:							
Corrective Action:							
Date:							

**Inspected Facilities**

Facility ID: 215854 Type: WELL API Number: 067-07459 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500137	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791834">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791834</a>