

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2022

Submitted Date:

06/29/2022

Document Number:

702500138

**FIELD INSPECTION FORM**Loc ID 306820 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268702	WELL	PR	08/07/2017	GW	067-08840	SIMON LAND & CATTLE 27-01 2	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Well sign is deteriorated and not legible (IMG 01).		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/28/2022

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds present at produced water tank and around location (IMG 03).		
Corrective Action:	Control weeds to comply with rule 606.	Date:	07/13/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Pump jack, separator, gas meter run, and produced water tank are enclosed by stock panel.		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	2 rig anchors not marked properly (IMG 04).		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	07/13/2022
Type: Gas Meter Run	# 1		
Comment:	Meter calibration is within last year.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2	
Comment:	Telemetry, Lube oil	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	Separator vent stack screened properly.	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Gas powered	
Corrective Action:		Date:
Type: Flow Line	# 4	
Comment:	3" and 2" line from wellhead to separator, 1" line from wellhead to prime mover, line from separator to produced water.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.157707,-107.817242
Comment:	Partially buried produced water tank.				
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	cone top

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal secondary containment.			
Corrective Action:			Date:	

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: 268702	Type: WELL	API Number: 067-08840	Status: PR
Insp. Status: PR			
Producing Well			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass					
Gravel	Pass					
		Compaction	Pass			

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500139	photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791835">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791835</a>