

Inspection Photos

API: 071-09521

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/28/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 6/28/2022

Inspection Photos



Photo 1. Facing southwest at the location. The location has not been recontoured and a steep cut slope remains. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 6/28/2022

Inspection Photos



Photo 2. There is a pit that remains along the base of the cut slope at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 6/28/2022

Inspection Photos



Photo 3. Facing southeast toward the pit at the base of the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 6/28/2022

Inspection Photos



Photo 4. There are 3 steel casings that remain at center of the location. The casing shown at red arrow is not covered to prevent entry. The steel casings need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 6/28/2022

Inspection Photos



Photo 5. Facing southeast toward the location. The abandoned location needs to be recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 6/28/2022

Inspection Photos



Photo 6. Facing west along the fill slope of the location which will need to be recontoured back into the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 6/28/2022

Inspection Photos



Photo 7. There are some signs of erosion at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09521 | Date: 6/28/2022