

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2022

Submitted Date:

06/29/2022

Document Number:

700704355**FIELD INSPECTION FORM**Loc ID 334696 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211295	WELL	PR	07/17/1996	GW	045-07054	MAMM CREEK 12-33-6-92	PR
285506	WELL	PR	07/06/2006	GW	045-12493	MAMM CREEK FEDERAL 13B-33-692	PR
285508	WELL	PR	11/01/2006	GW	045-12492	MAMM CREEK FEDERAL 13D-33-692	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 6/27/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Mamm Creek Fed 12-33, at Location # 334696 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following possible compliance issues were observed:

1. Stored equipment (ECD is disconnected from everything)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	STORAGE OF SUPL			
Comment:	Stored equipment (ECD is disconnected from everything)			
Corrective Action:	Remove stored equipment.			Date: 08/10/2022
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Emission Control Device	# 1			corrective date
Comment:	See stored equipment			
Corrective Action:				Date:
Type: Gas Meter Run	# 3			
Comment:				

Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	1 chemical tank in plastic containment and 1 500 gallon methanol tank in metal containment.		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Inspector Name: Ramsey, Scott

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 211295 Type: WELL API Number: 045-07054 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 285506 Type: WELL API Number: 045-12493 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 285508 Type: WELL API Number: 045-12492 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Ditches						
Berms						
		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704361	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5792490">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5792490</a>