

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2022

Submitted Date:

06/23/2022

Document Number:

702500112**FIELD INSPECTION FORM**Loc ID 306966 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285561	WELL	PR	07/12/2006	CBM	067-09199	EMMETT WOLTER 2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location				
Lease Road:				
Type	Main			
comment:	Gravel main road			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date:
Corrective Action:				Date:
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	9 unused hammer unions surrounding wellhead (IMG 03 and IMG 04).			
Corrective Action:				Date:
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment associated with not in use flow line (IMG 05).			
Corrective Action:	Use or remove unused equipment per rule 606.			Date: 07/22/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Wellhead, separation equipment, gas meter run, and produced water tank enclosed by stock panel.			
Corrective Action:				Date:
Type	LOCATION			
Comment:	Location enclosed by barbed wire fencing.			
Corrective Action:				Date:
Equipment:				
Type: Prime Mover	# 1			corrective date
Comment:	Electric prime mover.			
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Telemetry, electric meter and panel, electric cabinet.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Calibration record is up to date.			
Corrective Action:				Date:

Type: Flow Line	# 4	
Comment:	In use: 3" line from wellhead to separator, 2" line from separator to gas meter run, line from separator to produced water tank. Not in use: 1/2" flow line on northwest corner of pump jack (IMG 05).	
Corrective Action:	If flow line is planned to be used again: apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3) If flow line is not planned to be used: complete flowline abandonment to comply with Rule 606.	Date: 07/19/2022
Type: Bird Protectors	# 1	
Comment:	Separator vent stack screened properly.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Bradenhead is accessible.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.259357,-107.617549
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	Produced water
Other (Capacity)	95 bbl
Other (Type)	Cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal secondary containment.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 285561	Type: WELL	API Number: 067-09199	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Gravel	Pass					
		Compaction	Pass			
Rip Rap	Pass					Rip rap run off on
Compaction	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403088483	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5787991
702500113	Photo Doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5787988