


Inspection Photos
Location Name: Keating 2
Location ID: 306900



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Lube oil has begun to impact material