

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2022

Submitted Date:

06/30/2022

Document Number:

702500149**FIELD INSPECTION FORM**Loc ID 306900 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275324	WELL	PR	12/27/2004	CBM	067-09001	KEATING 2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Lube oil at wellhead has begun to impact material (IMG 03).

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

OTHER

Comment: Wellhead, produced water tank, separator, and gas meter run are enclosed by stock panel.

Corrective Action:

Date:

Equipment:

corrective date

Type: Flow Line

4

Comment: 3" and 2" line from wellhead to separator, line from separator to produced water, 4" line from gas meter run to off location.

Corrective Action:

Date:

Type: Bird Protectors

1

Comment: Separator vent stack is screened properly.

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: Gas meter calibration is within the last year.

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

2

Comment: Telemetry, pump control panel

Corrective Action:

Date:

Type: Bradenhead

1

Comment: Bradenhead is accessible.

Corrective Action:

Date:

Type: Other

1

Comment: Lube oil container.		Date:
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: Gas powered		Date:
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.248620,-107.620095
Comment: Partially buried produced water tank.					Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Metal secondary containment.				Date:
Corrective Action:				Date:

Venting:

Yes/No		Date:
Comment:		Date:
Corrective Action:		Date:

Flaring:

Type		Date:
Comment:		Date:
Corrective Action:		Date:

Inspected Facilities			
Facility ID: 275324	Type: WELL	API Number: 067-09001	Status: PR
Insp. Status: PR			
Producing Well			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Compaction	Pass					
		Compaction	Pass			
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			
		Culverts	Pass			
Gravel	Pass					
Ditches	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500150	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5792754