

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/30/2022

Submitted Date:

06/30/2022

Document Number:

697006124

**FIELD INSPECTION FORM**
 Loc ID 329607 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone | Email                    | Comment |
|--------------|-------|--------------------------|---------|
| ,            |       | cogccinspection@pdce.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 249790      | WELL | PR     | 09/01/2020  | GW         | 123-17593 | KAMMERZELL 6-7F | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| <b>Fencing/:</b>   |                   |       |  |
| Type               | SEPARATOR         |       |  |
| Comment:           | Livestock fencing |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | WELLHEAD          |       |  |
| Comment:           | Panel             |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | TANK BATTERY      |       |  |
| Comment:           | Livestock fencing |       |  |
| Corrective Action: |                   | Date: |  |

|                               |                             |       |                 |
|-------------------------------|-----------------------------|-------|-----------------|
| <b>Equipment:</b>             |                             |       | corrective date |
| Type: Plunger Lift            | # 1                         |       |                 |
| Comment:                      |                             |       |                 |
| Corrective Action:            |                             | Date: |                 |
| Type: Gas Meter Run           | # 1                         |       |                 |
| Comment:                      | Calibration card is current |       |                 |
| Corrective Action:            |                             | Date: |                 |
| Type: Emission Control Device | # 2                         |       |                 |

|  |     |       |
|--|-----|-------|
| Comment: <a href="#">Pilots are on</a>                           |     | Date: |
| Corrective Action:   |     | Date: |
| Type: Bradenhead   | # 1 |       |
| Comment: <a href="#">Bradenhead valve is exposed at surface.</a> |     |       |
| Corrective Action:   |     | Date: |
| Type: Flow Line  | # 1 |       |
| Comment:   |     |       |
| Corrective Action:   |     | Date: |
| Type: Bird Protectors  | # 4 |       |
| Comment:   |     |       |
| Corrective Action:   |     | Date: |
| Type: Horizontal Heated Separator                                | # 2 |       |
| Comment:   |     |       |
| Corrective Action:   |     | Date: |
| Type: Ancillary equipment  | # 3 |       |
| Comment: <a href="#">Automation array and two ECD scrubbers</a>  |     |       |
| Corrective Action:   |     | Date: |

**Tanks and Berms:**

| Contents                         | # | Capacity  | Type         | Tank ID | SE GPS |
|----------------------------------|---|-----------|--------------|---------|--------|
| PRODUCED WATER                   | 2 | <100 BBLs | PBV CONCRETE |         | ,      |
| Comment: <a href="#">53 bbls</a> |   |           |              |         |        |
| Corrective Action:               |   |           |              |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
| Date:              |          |                     |                     |             |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 2 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |

Other (Type)

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 249790 Type: WELL API Number: 123-17593 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 04/13/2021Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697006125    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5793375">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5793375</a> |