

Construction and Stormwater Inspection

June 16, 2022

Operator: CCRP OPERATING INC- 10665

Location ID: 455554

Inspection Document #: 697504022

Weld County, CO

SESE Section 27 T12N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: True Ranch Fee /27 East
Location ID: 455554



Photo 1. Photo taken from the northern location on the topsoil stockpile, facing South. Photo illustrates the Operator has not performed drilling operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697500020

Inspection Photos
Location Name: True Ranch Fee /27 East
Location ID: 455554



Photo 2. Photo taken from the northern location on the topsoil stockpile, facing Southwest. See comments under Photo 1.



Photo 3. Photo taken from the northern location on the topsoil stockpile, facing Southeast. See comments under Photo 1.

Inspection Photos
Location Name: True Ranch Fee /27 East
Location ID: 455554



Photo 4. Photo taken from the southern location, facing East. Photo illustrates the vegetative growth that is both native and introduced plant species.

Inspection Photos
Location Name: True Ranch Fee /27 East
Location ID: 455554



Photo 5. Photo taken from the southeastern location, facing East. Photo illustrates the detention pond that is in proper functioning condition.



Inspection Photos
Location Name: True Ranch Fee /27 East
Location ID: 455554



Photo 6. Photo taken from the northeastern location, facing Northeast. Photo illustrates the detention pond that is in proper functioning condition.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697500020

Inspection Photos
Location Name: True Ranch Fee /27 East
Location ID: 455554



Photo 7. Photo taken from the northeastern location, facing West. Photo illustrates a silt fence BMP is disrepair. There appears to be sufficient vegetative growth that the silt fence may not be needed any further since there is a ditch BMP to the interior that is directed to a detention area.



Inspection Photos
Location Name: True Ranch Fee /27 East
Location ID: 455554



Photo 8. Photo taken from a portion of the main lease road, facing East. Photo illustrates desirable vegetation is observed but cheatgrass is starting to establish along areas of the access road.

Inspection Photos
Location Name: True Ranch Fee /27 East
Location ID: 455554




Photo 9. Photo taken from a portion of the main lease road (approximately halfway), facing Southeast. Photo illustrates an area where topsoil was stockpiled from the access road. This area will need to meet Rule 1004 vegetative standards.