

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2022

Submitted Date:

07/01/2022

Document Number:

688801174**FIELD INSPECTION FORM**Loc ID 453364 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100382Name of Operator: CANFIELD DRILLING COMPANYAddress: BOX 453City: FT MORGAN State: CO Zip: _____**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Roy, Catherine		catherine.roy@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	
Chollett, Shannon		shannon.chollett@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453363	WELL	TA	12/15/2017	GW	077-10548	Canfield (OWP) 1	EI

General Comment:

On June 22, 2022 COGCC OWP Western Region EPS Jim Hughes conducted an environmental field inspection of the Canfield (OWP) #1. For the most recent field inspection report of this facility, please refer to document #692200651. The OWP Western Region Supervisor was on site during this inspection.

Inspected Facilities

Facility ID: 453363 Type: WELL API Number: 077-10548 Status: TA Insp. Status: EI

COGCC Comments

Comment	User	Date
<p>On June 22, 2022 COGCC OWP Western Region EPS Jim Hughes conducted an environmental field inspection of the Canfield (OWP) #1. For the most recent field inspection report of this facility, please refer to document #692200651. The OWP Western Region Supervisor was on site during this inspection.</p> <p>The area adjacent to the Canfield (OWP) #1 is saturated with fluids and has gas bubbling to the surface.</p> <p>On 6/27/22 a telephone conversation between the USACE's regional office and the COGCC's OWP concluded that no action was to be required by the USACE regarding wetland delineation prior to the OWP plugging and abandoning this well. This determination was made due to the fact that the area had artificial hydrologic connectivity. Field observations during this inspection appear to indicate that the Canfield (OWP) #1 has created a pathway for fluid migration to the surface.</p> <p>Fluid samples will be collected from the area adjacent to the Canfield (OWP) #1 prior to any surface disturbance.</p>	hughesjo	07/01/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801175	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5794266