

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2022

Submitted Date:

07/03/2022

Document Number:

707600002**FIELD INSPECTION FORM**Loc ID 427198 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427676	WELL	TA	03/01/2022	OW	123-35074	BALL RANCH AC 15-65HN	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations: Cementing. Initial plugs.

Battery: Inactive | Shut-down.

Inactive Battery SE corner GPS coordinates: 40.577718 / -104.430295

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Jobsite safety signage present.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
	Date:	<input type="text"/>	

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Iron pipe.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Iron panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Gas engine drives pump jack. Shut-down.		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:	Shut-down.		
Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 427676 Type: WELL API Number: 123-35074 Status: TA Insp. Status: PA

**Cement**Cement ContractorContractor Name: A-Plus

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 6887'-2150'Cement Volume (sx): 24 sxs

Good Return During Job: \_\_\_\_\_

Cement Type: Class "G" Neat 15.8#Comment:

Workover Contractor: A-Plus. Rig #12.  
Cement Contractor: A-Plus.

## Reference:

Form 6N on file. Notice of Intent to Abandon date: 06/01/2022. Approved.

Form 42 on file. Notice of MIRU. Start Date: 05/04/2022. Approved.

Form 42 on file. Notice of Plugging Operations. Start Date: 05/04/2022. Approved.

Plugging Operations: Cementing. Initial plugs.

SAFETY MEETING,CHECK PSI,CSG 10 PSI,SURFACE O PSI,TIH W/2.875 6.5#  
TBG,TAG 2 SAC CMT PLUG @6 887,LOAD HOLE V1'15 BBLS,CIRCULATE 40 BBLS  
GETTING OILAND GAS IN RETURNS,PUMP 10 BBLS CHEM WASH,20 SACS OR 4  
BBLS OF 15.8#  
G-NEAT CMT @1.15 YIELD,DISPLACE 35 BBLS OF FRESH WATER,TOOH LD 221  
JTS,RUWL,PU 7 26# CIBP & SET @2150,LOG FROM 1500 TO SURFACE,PU 3.125  
DUMP BAILER & SPOT 2 SACS CMT ON CIBP,RDWL SWI.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 06/28/2022 at approximately 16:44 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: BALL RANCH AC /15-65HN  Location ID: 427198  Well Name(s):  Ball Ranch AC 15-65HN.  API: 123-35074.  Location County: Weld County, Colorado  Weather: Partly Sunny, dry.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Plugging Operations: Cementing. Initial plugs.  Battery: Inactive   Shut-down.  Inactive Battery SE corner GPS coordinates: 40.577718 / -104.430295</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/03/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707600003	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5794428">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5794428</a>