

Inspection Photos

API: 055-06142

Operator: CAPTUREPOINT LLC

Inspection Date: 7/1/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/1/2022

Inspection Photos



Photo 1. Facing north along the access road. There are noxious weeds along the road that need to be controlled. Red arrow → Scotch thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/1/2022

Inspection Photos



Photo 2. Facing northeast toward the multi well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/1/2022

Inspection Photos



Photo 3. Well sign is posted at the well head and has been updated with current operator INFO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/1/2022

Inspection Photos



Photo 4. Facing toward the north side of the location. There are noxious weeds along the north side of the location that need to be controlled. Red arrow → Musk thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/1/2022