

Inspection Photos
Location Name: Huber Crook 4-26
Location ID: 326530



IMG 01
Well sign



IMG 02
Location overview




IMG 03

Unused equipment



IMG 04

Unused equipment



IMG 05

Lube oil on gas meter run/separator house floor has begun to impact surface material



IMG 06

Trash near separator house



IMG 07

Rig anchor not marked