

Inspection Photos

API: 055-06301

Operator: CAPTUREPOINT LLC

Inspection Date: 7/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06301 | Date: 7/1/2022

Inspection Photos



Photo 1. Facing west at the entrance of the Gas Plant. There are noxious weeds along the road that need to be controlled. Red arrow → Diffuse knapweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 7/1/2022

Inspection Photos



Photo 2. Facing west at the entrance of the Gas Plant. There are noxious weeds along the road that need to be controlled. Red arrow → Hoary Crest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 7/1/2022

Inspection Photos



Photo 3. Facing southwest along the access road. There are noxious weeds that need to be controlled. Red arrow → Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 7/1/2022

Inspection Photos



Photo 4. Facing northeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 7/1/2022

Inspection Photos



Photo 5. Well sign is posted at the well head and has been updated with current operator INFO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 7/1/2022

Inspection Photos



Photo 4. Facing toward the north side of the location. There are noxious weeds along the north side of the location that need to be controlled. Red arrow → Musk thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 7/1/2022