

Inspection Photos
Kern UPPR 41-5 1 O SA Facility
Spill ID 482122 (CL) /Remediation Project No 22664



Photo 1 – Location sign



**Photo 2 – Location photo. Fencing is down.
Groundwater observed in open excavation.
Groundwater is covered with bird netting.**

Inspection Photos
Boulter Tank Battery Spills
Spill ID 481624 (CL) & 481638 (CL)/Remediation Project No 21306



Photo 3 – Downed fencing in open excavation.



Photo 4 – Open excavation.

Inspection Photos
Boulter Tank Battery Spills
Spill ID 481624 (CL) & 481638 (CL)/Remediation Project No 21306



Photo 5 – Open excavation



Photo 6 – Clean stockpiled soils on location.