

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2022

Submitted Date:

06/30/2022

Document Number:

701601870

FIELD INSPECTION FORM

Loc ID 312178 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dizghinjili, Victoria		vdizghinjili@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219278	WELL	TA	02/12/1996	OW	075-06127	KNUDSEN 1	TA

General Comment:

[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Repair and maintain lease road.		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	No sign at wellhead.		
Corrective Action:	Comply with Rule 605 series.	Date:	08/30/2022

Emergency Contact Number:			
Comment:	No emergency contact info. on signage (no sign) at wellhead.		
Corrective Action:	Comply with Rule 605 series.	Date:	07/30/2022

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No
 Comment: NONE

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 0		
Comment:	Well has been SI, preparing well to return to PR.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 219278 Type: WELL API Number: 075-06127 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: Well is in process of returning to PR. Well is directly adjacent to primary inlet ditch to North Sterling Reservoir and North Sterling State Park. Wellhead is located directly upslope from inlet ditch. Consider installing structures/appliances for containment of potential release/spill from wellhead. See photographs

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403094523	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5793687
701601874	Photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5793676