

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/30/2022

Submitted Date:

06/30/2022

Document Number:

701601872**FIELD INSPECTION FORM**Loc ID 312250 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dizghinjili, Victoria		vdizghinjili@kpk.com	<a href="#">All inspections</a>
Lindley, Trent		trent.lindley@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Quint, Craig		craig.quint@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219870	WELL	PR	11/01/2019	OW	075-07533	KNUDSEN 7	PR

**General Comment:**

Follow-up FIR - Doc# 701601246, 701600868, 699602115, 699600431, 699601657. CA's cited in previous FIR's have not been performed. All CA dates are past due. See attached photographs for referencing conditions. Facility ID tied to current PR well 05-075-07533 - Knudsen 7.

NOTE TO OPERATOR: Please read FIR completely, perform CA's and submit FIRR with current photographs showing CA's have been performed. All previous and current CA's remain in effect until approved by COGCC.

**Location****Lease Road:**

Type	Access		
comment:	Repair-restore and maintain lease roads		
Corrective Action	Repair and maintain lease road to comply with Rule 204	Date:	05/08/2022

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	TRASH		
Comment:	Remove spill absorbant materials from inside berm floor. See photos		
Corrective Action:	Comply with Rule 606	Date:	04/23/2022
Type	DEBRIS		
Comment:	Remove all concrete debris from abandoned debris pile adjacent to PW tanks/pits. CA dates past due		
Corrective Action:	Comply with Rule 606	Date:	03/23/2022
Type	OTHER		
Comment:	Remove all abandoned flow-lines (west) of tank battery and transfer shed.		
Corrective Action:	Comply with Rule 1105. Contact COGCC FLOW-LINE GROUP FOR DIRECTIVES	Date:	04/06/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
Lube Oil	Flow Line			
Comment:	Remove from location to appropriate disposal site, do not spread contaminated soils upon berms, do not cover stained/saturated soils with clean dirt/gravel. Contaminated soils remain present within transfer shed. See photographs			
Corrective Action:	Comply with Rule 906 & 905.e			Date: 03/11/2022

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 0		corrective date
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	No change in tank/berm configuration.					
Corrective Action:					Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 219870 Type: WELL API Number: 075-07533 Status: PR Insp. Status: PR

**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type:                      Size:                      Material:  
 Variance:                      Age:                      Contents:

Integrity Summary

Failures:                      Spills:                      Repairs Made:  
 Coatings:                      H2S:                      Cathodic Protection:

Pressure Testing

Witnessed:                      Test Result:                      Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☐ 1102. Operations, Maintenance, and Repair    ☐ 1103. Abandonment

Comment:

Corrective Action:

Date:

## Environmental

### Spills/Releases:

Type of Spill: _____	Estimated Spill Volume: _____
Comment: _____	
Corrective Action: _____	Date: _____
Reportable: _____	GPS: Lat _____ Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____

### Water Well Complaint:

		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

### Field Parameters:

Sample Location: _____	Comment: _____
------------------------	----------------

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Repair/Maintain lease roads for stormwater erosion management](#)Corrective Action: [Repair/Maintain lease roads for stormwater erosion management](#)

Date: 05/08/2022

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Follow-up FIR - All previous CA's dates have expired/past due.</a>	schureky	06/30/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403094458	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5793585">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5793585</a>
701601873	Photographs of location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5793584">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5793584</a>