

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2022

Submitted Date:

06/30/2022

Document Number:

702500144

FIELD INSPECTION FORMLoc ID 306890 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274089	WELL	PR	05/01/2020	CBM	067-08982	DWIGHT SOSSAMAN A 2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Lube oil has impacted material at wellhead (IMG 03).

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 07/14/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

LOCATION

Comment: Locatoin enclosed by barbed wire fence.

Corrective Action:

Date:

Type

WELLHEAD

Comment: Wellhead enclosed by stock panel.

Corrective Action:

Date:

Equipment:

corrective date

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: Bradenhead is accessible.

Corrective Action:

Date:

Type: Ancillary equipment

3

Comment: Telemetry, pump VFD panel, electric panel

Corrective Action:

Date:

Type: Flow Line

4

Comment: 3" and 2" line from wellhead to separator, line from separator to produced water, 4" line from gas meter run to off location.

Corrective Action:

Date:

Type: Bird Protectors

1

Comment: Separator vent stack is screened properly.

Corrective Action:

Date:

Type: Other

1

Comment: Gas powered generator.		Date:	
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: Meter calibration is within the last year.		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.246431,-107.603385
Comment: Partially buried produced water tank.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Metal secondary containment.				
Corrective Action:				
Date:				

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	274089	Type:	WELL	API Number:	067-08982	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Compaction	Pass			
Berms	Pass					run off berm
Gravel	Pass					
Compaction	Pass					

Comment: 2 stormwater channels have formed on southeast corner of location, ~10" wide by ~8" deep and ~10" wide and ~6" deep (IMG 04).

Corrective Action: Repair/modify required BMPs per Rule 1002.f.(2)C

Date: 07/14/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403093431	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5792756
702500148	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5792752