

<b>Today's Date:</b>	6/29/2022					
<b>Well Name:</b>	CARTER UTE 107	<b>Location:</b>	Sec: 13	Twn: 032N	Rng: 010W	UL: A
<b>API Number:</b>	05.067.07459	<b>Footage:</b>	1140' FNL & 1205' FEL			
<b>Operator:</b>	Hilcorp Energy Company	<b>Area/Run/MSO:</b>	01	0105	Pepe Frias Hernandez	
<b>Meter #:</b>	1910101		<b>Pipeline:</b>	RC		
<b>INC Number:</b>	702500136	<b>Agency:</b>	COGCC	<b>Inspector:</b>	Alex Klink	
<b>Type of INC:</b>	Written	<b>Photos Required:</b>	Yes	<b>Due Date:</b>	7/13/2022	
<b>Issue of Concern:</b>	<p><b>Comment:</b> Dirt access road is developing ruts. Above ground produced water tank signs beginning to deteriorate (IMG 10).</p> <p><b>Comment:</b> Unused equipment at wellhead (IMG 06). Unused equipment at southern separator (IMG 05).</p> <p><b>Corrective Action:</b> Use or remove unused equipment per rule 606.</p> <p><b>Comment:</b> Impacted material at oil container north of compressor skid (IMG 07). Impacted material west of partially buried produced water tank (IMG 08). Impacted material west of compressor skid (IMG 09).</p> <p><b>Corrective Action:</b> Remove impacted material per rule 906 and 1002.f.</p> <p><b>Comment:</b> Oil containers. 2 oil containers do not have spill prevention (IMG 03 and 04).</p> <p><b>Corrective Action:</b> Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.</p> <p><b>Comment:</b> Not in use: 2" line stubbed up near southern separator, with no lock out/tag out.</p> <p><b>Corrective Action:</b> Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3).</p>					

**From:** Ashton Hemphill <ahemphill@hilcorp.com> |

**Sent:** Thursday, July 7, 2022 5:10 AM

**To:** Tammy Jones <tajones@hilcorp.com>; Freddy Proctor <fproctor@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Shara De Velder <sdevelder@hilcorp.com>

**Subject:** RE: CARTER UTE 107 - INC - 702500136

I removed all unused equipment and installed new berms around the two oil day barrels.

I installed new Lock out / tag out tags on the two inch stubbed up line coming out of the ground.

We cleaned up all impacted soil and disposed of it and replaced with clean road base.



**CARTER UTE 107**

**LAT: 37.02101, LONG: -107.87959**

**UNIT A 1140' FNL & 1205' FEL**

**SEC. 13, T32N, R10W NE/NE**

**LEASE # 14-20-151-13A**

**API NO. 05-067-07459**

**LA PLATA COUNTY, CO ELEV 6204**

**EMERGENCY CONTACT (505) 324-5170 OR 911**

**NO SMOKING**

**NO TRESPASSING**









PRODUCED WATER

1 4 0

HAZARD

505-324-5170

Capacity 500 RL

Produced Water



























