

| | | | | | | |
|-------------------|---|------------------|----------------------|------------|----------------------|-------|
| Today's Date: | 6/29/2022 | | | | | |
| Well Name: | SEVER 1 | Location: | Sec: 13 | Twn: 032N | Rng: 010W | UL: H |
| API Number: | 05.067.05082 | Footage: | 1650' FNL & 990' FEL | | | |
| Operator: | Hilcorp Energy Company | Area/Run/MSO: | 01 | 0105 | Pepe Frias Hernandez | |
| Meter #: | 1920101 | | Pipeline: | RC | | |
| INC Number: | 702500134 | Agency: | COGCC | Inspector: | Alex Klink | |
| Type of INC: | Written | Photos Required: | Yes | Due Date: | 7/13/2022 | |
| Issue of Concern: | <p>Comment: Access road is both dirt and washed rock. Some sections of dirt road are developing ruts. Partially buried produced water tank.</p> <p>Comment: Unused equipment and trash in spill prevention for oil container (IMG 03).</p> <p>Corrective Action: Use or remove unused equipment per rule 606. Remove trash per rule 606.</p> <p>Comment: Not in use: 2" line stubbed up near gas meter run is not locked out/tagged out (IMG 04).</p> <p>Corrective Action: Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)</p> | | | | | |

From: Ashton Hemphill <ahemphill@hilcorp.com>

Sent: Thursday, July 7, 2022 4:56 AM

To: Tammy Jones <tajones@hilcorp.com>; Freddy Proctor <fproctor@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Shara De Velder <sdevelder@hilcorp.com>

Subject: RE: SEVER 1 - INC - 702500134

I got all unused equipment and trash off location and the two inch valve locked and tagged out.





