

**Inspection Photos**  
**Location Name: UPRR 43 Pan AM I #30**  
**Location ID: 318749**



**Photo 1 Well head**



**Photo 2 Weeds, unused equipment (cement base) Sign faded not legible.**





**Inspection Photos**  
**Location Name: UPRR 43 Pan AM I #30**  
**Location ID: 318749**



**Photo 3 unused electric lines**



**Photo 4 loc pic**



## Inspection Photos

Location Name: UPRR 43 Pan AM I #30

Location ID: 318749



Photo 5 Small leak on well head around tubing.

