

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/07/2022

Submitted Date:

07/07/2022

Document Number:

693507509

### FIELD INSPECTION FORM

Loc ID 318312 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>
,		dnr_cogccenforcement@state.co.us	
,	303-825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241092	WELL	PA	10/07/2019	GW	123-08880	UPRR 43 PAN AM I 10	PA

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: P&A operations surface equipment still onsite.

Corrective Action: Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well. All access roads to plugged and abandoned wells and associated production facilities shall be closed, graded and recontoured. Culverts and any other obstructions that were part of the access road(s) shall be removed. Well locations, access roads and associated facilities shall be reclaimed

Date: 12/02/2021

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Ancillary equipment

# 1

corrective date

Comment: Electric panel

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 241092 Type: WELL API Number: 123-08880 Status: PA Insp. Status: PA**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On Thursday June 7 2022 at approximately 09:24AM, I, Inspector Randy Silver,  Conducted an on-site re-inspection per Doc# 693505725.  Location: UPRR 43 Pan AM I10  Operator: KP Kauffman  API#:12308880  County: Weld  While there, I observed P&amp;A well site  During this inspection the following possible compliance issues were observed:  P&amp;A operations: Rule 1004a Corrective action date of 12-2-21 See photos 1,2  This is the second inspection with said violation. At time of inspection it appears no activity  has taken place on site.  Weather conditions: Dry and cloudy.  A follow up on this site inspection needs to be conducted to ensure the  compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	silverr	07/07/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693507510	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797393">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797393</a>