

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2022

Submitted Date:

07/07/2022

Document Number:

693507503**FIELD INSPECTION FORM**Loc ID 318801 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------|------------------|----------------------------------|
| , | 303-825-4822 | cogcc@kpk.com | All Inspections |
| Watzman, Ross | (303) 825-4822 | rwatzman@kpk.com | all inspections. |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 242187 | WELL | SI | 03/01/2022 | OW | 123-09978 | UPRR 43 PAN AM I 33 | PA |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 242187 Type: WELL API Number: 123-09978 Status: SI Insp. Status: PA

CementCement ContractorContractor Name: KPK

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 3370Cement Volume (sx): 10Good Return During Job: YES

Cement Type: _____

Comment: Set balance plug and placed 10 sks cement .

Corrective Action: _____

Date: _____

WorkoverComment: KPK workover rig and AXIS energy services cement truck. At time of inspection cew place 10 sks cement on balance plug.

Corrective Action: _____

Date: _____

Completion

Operation: _____

Date Flowback: _____

Contractor: _____

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

| Comment | User | Date |
|----------------------------------|---------|------------|
| <u>Inspection due to form 42</u> | silverr | 07/07/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 693507504 | loc pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797390 |