

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2022

Submitted Date:

07/07/2022

Document Number:

702500193**FIELD INSPECTION FORM**Loc ID 334403 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294243	WELL	PR	04/27/2022	GW	067-09477	MW JOHNSON A 4	PR
294389	WELL	PR	01/15/2008	CBM	067-09486	MW JOHNSON A 3	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash near A3 wellhead (IMG 07)		
Corrective Action:	Remove trash per rule 606.		Date: 07/15/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused metal tubing south of A2 wellhead (IMG 05), unused electrical conduit near electric cabinet (IMG 04), unused flex hose near compressor house (IMG 08)		
Corrective Action:	Use or remove unused equipment per rule 606.		Date: 07/23/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	All equipment on location enclosed by stock panel.		
Corrective Action:			Date:

**Equipment:**

			corrective date
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Telemetry, 2 pump control panels Equipment also associated with A2 well: Electric cabinet		
Corrective Action:			Date:
Type: Flow Line	# 7		
Comment:	2 3" and 2 2" lines from wellhead to separator, 4" line from gas meter run to off location, 2 lines from separator to produced water tank.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Linear rod pump		
Corrective Action:			Date:

Type: Gas Meter Run	# 2	
Comment:	Gas meter calibrations are within the last year.	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Electric	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:	Separator and tank vent stack are screened properly.	
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:	Compressor house near produced water tanks. This equipment is also associated with the A2 well.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		37.194542,-107.717622
Comment:	Above ground produced water tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	cone top

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Gravel and dirt earth berm secondary containment.			
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 294243 Type: WELL API Number: 067-09477 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 294389 Type: WELL API Number: 067-09486 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Gravel	Pass			
Compaction	Pass					
Rip Rap	Pass					
		Compaction	Pass			
Gravel	Pass					
Ditches	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500196	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797755">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797755</a>