

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/06/2022

Submitted Date:

07/07/2022

Document Number:

701005349

**FIELD INSPECTION FORM**

Loc ID 304206 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
 Address: 5057 KELLER SPRINGS RD STE 650  
 City: ADDISON State: TX Zip: 75001

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone          | Email                           | Comment |
|---------------|----------------|---------------------------------|---------|
| Jones, Greg   | (970) 630-3909 | greg.jones@ownresources.com     |         |
| Dolezal, Pat  | (970) 332-3585 | pat.dolezal@ownresources.com    |         |
| Beard, Alyssa |                | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 254195      | WELL | PR     | 08/01/2020  | GW         | 125-08073 | OSMUS 44-24   | PR          |

**General Comment:**

[Routine Inspection](#)

**Location**

|                    |                           |  |       |
|--------------------|---------------------------|--|-------|
| <b>Lease Road:</b> |                           |  |       |
| Type               | Access                    |  |       |
| comment:           | Trail through farm ground |  |       |
| Corrective Action: |                           |  | Date: |

Overall Good:

|                      |   |  |       |
|----------------------|---|--|-------|
| <b>Signs/Marker:</b> |   |  |       |
| Type                 | WELLHEAD                                |  |       |
| Comment:             | Lease sign mounted to fence at wellhead |  |       |
| Corrective Action:   |   |  | Date: |

|                                  |  |  |             |
|----------------------------------|--|--|-------------|
| <b>Emergency Contact Number:</b> |  |  |             |
| Comment:                         |  |  |             |
| Corrective Action:               |  |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

|                    |   |  |       |
|--------------------|---|--|-------|
| <b>Fencing/:</b>   |   |  |       |
| Type               | WELLHEAD                                  |  |       |
| Comment:           | Pipe fence around wellhead and metal shed |  |       |
| Corrective Action: |   |  | Date: |

|                           |                |  |                 |
|---------------------------|----------------|--|-----------------|
| <b>Equipment:</b>         |                |  | corrective date |
| Type: Gas Meter Run       | # 1            |  |                 |
| Comment:                  |                |  |                 |
| Corrective Action:        |                |  | Date:           |
| Type: Ancillary equipment | # 1            |  |                 |
| Comment:                  | Electric panel |  |                 |
| Corrective Action:        |                |  | Date:           |
| Type: Vertical Separator  | # 1            |  |                 |
| Comment:                  |                |  |                 |
| Corrective Action:        |                |  | Date:           |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Venting:</b>    |  |  |       |
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

|                 |  |  |  |
|-----------------|--|--|--|
| <b>Flaring:</b> |  |  |  |
| Type            |  |  |  |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 254195 Type: WELL API Number: 125-08073 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Downhole equipment still in wellbore](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Other                   | Pass                  |               |                          |         |

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 701005370    | location photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797844">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797844</a> |