

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2022

Submitted Date:

07/08/2022

Document Number:

702500200**FIELD INSPECTION FORM**Loc ID 306883 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273192	WELL	PR	01/27/2005	CBM	067-08959	DICKENS 44-14 2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused metal tubing at pump jack (IMG 04).		
Corrective Action:	Use or remove unused equipment per rule 606.	Date:	07/22/2022
Type	OTHER		
Comment:	Lube oil has impacted material at wellhead (IMG 03).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.	Date:	07/22/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Separator, produced water tank, and gas meter run are enclosed by stock panel.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Pump jack base enclosed by metal mesh fencing.		
Corrective Action:		Date:	

Equipment:

Type: Flow Line	# 5		corrective date
Comment:	2" and 3" line from wellhead to separator, 1" line from wellhead to prime mover, line from separator to produced water tank, 4" line from gas meter run to off location.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment: Telemetry, lube oil container		Date:
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Bradenhead is accessible.		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment: Separator vent stack is screened properly.		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.193931,-107.681062
Comment: Partially buried produced water tank.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Metal secondary containment.				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: <u>273192</u>	Type: <u>WELL</u>	API Number: <u>067-08959</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:				
Corrective Action:				Date: <div></div>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Gravel	Pass			
Ditches	Pass					
Rip Rap	Pass					
Gravel	Pass					
		Compaction	Pass			
Check Dams	Pass					

Comment: Stormwater channel has formed on southeast corner of location (IMG 05). Channel is ~6" wide and ~4" deep, and extends ~4' above established rip rap run off. Channel is encroaching on produced water tank secondary containment. Facilities must be operated in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C

Date: 07/22/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500201	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797983