

Inspection Photos and Issue Report

7/7/2022

Operator: CHEVRON USA INC - 16700

Location ID: 314945

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314945



July 7, 2022



July 7, 2022

Photo 1: Photos taken from the northeast end of the Location. Photos provide an overview of the Location facing southwest to west. Photos examples showing Location is either bare, or predominantly vegetated by Undesirable and Noxious Plant Species, such as Halogeton, cheatgrass, and annual wheatgrass



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314945



Photo 2: Photo taken from the north end of the Location, facing south. Photo shows Location is either bare, or predominantly vegetated by Undesirable and Noxious Plant Species, such as Halogeton, cheatgrass, and annual wheatgrass

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314945



Photo 3: Photo shows Halogeton establishment on the Location.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314945



Photo 4: Photo taken from the bare areas of the Location. Photo shows Reclamation Specialist attempted to dig a test pit, but was only able to easily penetrate the first couple inches of soil. Compaction concerns evident at the Location and access road; compaction alleviation inadequate and does not appear to have been conducted.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314945



Photo 5: Photos of access road. Access road is either bare, or predominantly vegetated by Undesirable and Noxious Plant Species, such as Halogeton, cheatgrass, and annual wheatgrass

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314945



Photo 6: Photos taken from the bare areas of the Access Road. Photo shows Reclamation Specialist attempted to dig a test pit, but was only able to easily penetrate the first couple inches of soil. Compaction concerns evident at the Location and access road; compaction alleviation inadequate and does not appear to have been conducted. Photo also shows gravel/road base remaining.