

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2022

Submitted Date:

07/08/2022

Document Number:

696203844**FIELD INSPECTION FORM**Loc ID 421429 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 760 HORIZON DRIVE STE 401City: GRAND JUNCTION State: CO Zip: 81506**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone | Email                         | Comment       |
|------------------|-------|-------------------------------|---------------|
| Patterson, Chris |       | Chris.Patterson@scoutep.com   |               |
| ,                |       | RangelyRegulatory@scoutep.com | Rangely Field |
| Sanford, Anita   |       | Anita.Sanford@scoutep.com     | Rangely Field |
|                  |       | andrewolson@chevron.com       |               |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|----------------|-------------|
| 421429      | LOCATION | AC     |             |            | -         | FEE 160X -161X | RI          |
| 422432      | WELL     | PR     | 02/01/2022  | OW         | 103-11866 | FEE 160X       | RI          |

**General Comment:**

On 7/7/2022, Reclamation Specialist Trujillo inspected the FEE /160X -161X location in Rio Blanco County, Colorado.

Chevron is currently the Operator on record for the well and Location, however, a Form 9 is currently "in process" transferring ownership of the Location from Chevron USA Inc, to Scout Energy Management LLC; inspection is being submitted to both "Chevron" and "Scout".

The following compliance issues were observed during this inspection:

- Unused Equipment
- Weeds
- Fluids within containment

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: 970-675-3700, Wellhead

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | UNUSED EQUIPMENT  |       |            |
| Comment:           | Unused ladder/step equipment observed on east end of the Location |       |            |
| Corrective Action: | Comply with Rule 606  | Date: | 07/23/2022 |

Overall Good: ☐

|                    |   |        |  |                  |
|--------------------|---|--------|--|------------------|
| <b>Spills:</b>     |   |        |  |                  |
| Type               | Area  | Volume |  |                  |
|                    |   |        |  |                  |
| Comment:           | Fluids observed within secondary containment at the Methanol tank |        |  |                  |
| Corrective Action: | Remove and properly dispose fluids per 912.a                      |        |  | Date: 07/23/2022 |

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |        |       |          |               |           |         |               |               |    |
|----------------------|--------|-------|----------|---------------|-----------|---------|---------------|---------------|----|
| Facility ID:         | 421429 | Type: | LOCATION | API Number: - | Status:   | AC      | Insp. Status: | RI            |    |
| Facility ID:         | 422432 | Type: | WELL     | API Number:   | 103-11866 | Status: | PR            | Insp. Status: | RI |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? PassComment [Anchors marked per 1003.a](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ F \_\_\_\_\_

Comment Undesirable and Noxious Plant Species, including Halogeton, observed on the Location.

Corrective Action Comply with Rule 1003.f and 606.

Date 07/23/2022

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_

Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs   | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment                    |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|----------------------------|
|  |                 |                         |                       |               |                          |                            |
| <p>Comment: <a href="#">Unclear at time of inspection if pad is adequately stabilize to minimize degradation and sediment transport during wet conditions; however no immediate stormwater concerns were observed.</a></p> <p><a href="#">Continue to monitor and manage stormwater on Location, implement/maintain BMPs as needed per Rule 1002.f</a></p> |                 |                         |                       |               |                          |                            |
| Corrective Action: <input type="text"/>  |                 |                         |                       |               |                          | Date: <input type="text"/> |
| <b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT   |                 |                         |                       |               |                          |                            |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 696203845    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798651">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798651</a> |