

Inspection Photos

API: 017-06051

Operator: KUENZLER & FLORA RESERVE COMPANY

Inspection Date: 7/6/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-06051 | Date: 7/6/2022

Inspection Photos



Photo 1. Facing toward the well site. There is a bucket pipe riser at the wellhead area. It is unknown if the well has plugged per the 6N.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06051 | Date: 7/6/2022

Inspection Photos



Photo 2. There is some cement waste left near the well head. This needs to be cleaned up and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06051 | Date: 7/6/2022