

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2022

Submitted Date:

07/05/2022

Document Number:

696203822

**FIELD INSPECTION FORM**

Loc ID 334983 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                     | Comment                         |
|--------------|-------|---|---------------------------------|
| , "          |       | COGCC.inspections@caerus<br>oilandgas.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num | Facility Name                        | Insp Status |
|-------------|----------|--------|-------------|------------|---------|--------------------------------------|-------------|
| 334983      | LOCATION | AC     |             |            | -       | Federal Multi Well 28-5BB<br>(PA-29) | RI          |

**General Comment:**

On 7/1/2022, Reclamation Specialist conducted an inspection at Caerus Piceance LLC's Federal Multi Well 28-5BB (PA-29) Location in Garfield County, Colorado.

This inspection is a follow-up to #696203624 to document compliance with the following corrective action

- Stormwater
- Good Housekeeping

This inspection is also in response to Resolution #403051496 stating CAs Completed

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and Corrective actions.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

UNUSED EQUIPMENT

Comment:

Unused pipe equipment has been removed. CA completed

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:



**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Inspection #696203624 observed that the inlet at the sediment trap on the north end of the Location has not been installed per good engineering practices, or maintained in proper functioning condition, resulting in gully erosion and degradation at the control

It was observed in this inspection that the control measure has not been installed per good engineering practices; gully erosion has been repaired, however soils have been left unconsolidated, and the inlet has not been properly engineered and armored.

This CA has not been addressed.

Corrective Action: Original corrective action and date remains applicable.

Comply with 1002.f.; install or repair BMPs per good engineering practices, and maintain in proper functioning condition.

Date: 05/11/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403096554    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5795293">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5795293</a> |
| 696203823    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5795283">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5795283</a> |