

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2022

Submitted Date:

07/05/2022

Document Number:

702500164**FIELD INSPECTION FORM**Loc ID 326147 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|---------------------------------------|--------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , General | | FarmingtonRegulatoryTechs@hilcorp.com | All SW field inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 215946 | WELL | PR | 04/12/2000 | CBM | 067-07551 | HUBER-LOBATO 1-26 | PR |

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

| | | | |
|--------------------|---|--|------------------|
| Type | DEBRIS | | |
| Comment: | Construction debris on fill slope on southeast corner of location (IMG 07). | | |
| Corrective Action: | Remove debris per rule 606. | | Date: 07/19/2022 |
| Type | TRASH | | |
| Comment: | Trash on southeast corner of location (IMG 04). | | |
| Corrective Action: | Remove trash to comply with rule 606. | | Date: 07/12/2022 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment at pump jack (IMG 03). | | |
| Corrective Action: | Use or remove unused equipment per rule 606. | | Date: 07/19/2022 |
| Type | OTHER | | |
| Comment: | Impacted material at wellhead (IMG 06). Impacted material at exhaust muffler hose (IMG 05). | | |
| Corrective Action: | Remove impacted material and dispose of in approved manner per rule 906 and 1002.f. | | Date: 07/19/2022 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|--|--|-------|
| Type | PUMP JACK | | |
| Comment: | Pump jack is enclosed on 3 sides by sound panel. | | |
| Corrective Action: | | | Date: |

Equipment:

| | | | |
|--------------------------|--|--|-----------------|
| Type: Prime Mover | # 1 | | corrective date |
| Comment: | Gas powered prime mover. | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | Separator vent stack is screened properly. | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 4 | | |

| | | | |
|---------------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Gas meter calibration is within the last year. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead is accessible. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | Telemetry, lube oil tank at pump jack, tracer wire conduit | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 6 | | |
| Comment: | 3" and 2" line from wellhead to separator, 1" line from wellhead to generator, 2" and 3" line from separator to off location, 1" line at separator | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | | |
|-----------------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 215946 | Type: WELL | API Number: 067-07551 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Retention Ponds | Pass | | | | | |
| | | Gravel | Pass | | | |
| Compaction | Pass | | | | | |
| Ditches | Pass | | | | | |
| Berms | Pass | | | | | |
| Gravel | Pass | | | | | |
| | | Compaction | Pass | | | |
| | | | | Material Handling And Spill Prevention | Pass | |
| Rip Rap | Pass | | | | | |

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403095694 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5794710 |
| 702500168 | Photo doc | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5794701 |