

# Interim Reclamation and Stormwater Inspection

June 16, 2022

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 439459

Inspection Document #: 697504024

Weld County, CO

SESE Section 28 T12N R65W

Chris Binschus  
Reclamation Specialist, COGCC




**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources<sub>S</sub>

Inspection Photos  
Location Name: Motu East /2821-8CH  
Location ID: 439459



**Photo 1.** Photo taken from the southeastern location, facing Northwest. Photo illustrates debris that needs to be removed.



**Photo 2.** Photo taken from the southeastern location, facing East. Photo illustrates a List B Colorado noxious weed, toadflax.



Inspection Photos  
Location Name: Motu East /2821-8CH  
Location ID: 439459



**Photo 3.** Photo taken from the wellhead. Photo illustrates production facility equipment is not in good mechanical condition per Rule 608.e.



**Photo 4.** Photo taken from the wellhead. Photo illustrates unused equipment.



Inspection Photos  
Location Name: Motu East /2821-8CH  
Location ID: 439459



**Photo 5.** Photo taken from the wellhead. Photo illustrates unused equipment.



**Photo 6.** Photo taken from the northern interim reclamation area, facing East. Photo illustrates interim reclamation has been performed; however, an introduced seed mix was used which is not reflective of reference area vegetation per Rule 1003.



Inspection Photos  
Location Name: Motu East /2821-8CH  
Location ID: 439459



**Photo 7.** Photo taken from the entrance of location off CR 136. Photo illustrates damaged culverts that need to be repaired.

