

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2022

Submitted Date:

07/12/2022

Document Number:

702500214

## FIELD INSPECTION FORM

 Loc ID 378718 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 69805  
 Name of Operator: PETROX RESOURCES INC  
 Address: 12600 W COLFAX AVENUE #C-440  
 City: LAKEWOOD State: CO Zip: 80215
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 17 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Nystrom, Dusty	(505) 330-1328/ (719) 529-0682	nystrw@yahoo.com	<a href="#">All SW field inspections</a>
Clark, Ryan		ryan@petrox-resources.com	<a href="#">All SW field inspections</a>
Duran, Alicia		alicia.duran@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301886	WELL	PR	04/01/2021	CBM	007-06277	WRIGHT 33-5 16-1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds beginning to encroach on interim revegetation (IMG 04).		
Corrective Action:			Date:
Type	TRASH		
Comment:	Trash near pump jack (IMG 03).		
Corrective Action:	Remove trash per rule 606.		Date: <u>07/20/2022</u>

Overall Good:

**Spills:**

Type	Area	Volume	
------	------	--------	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Pump jack enclosed by mesh fencing.		
Corrective Action:			Date:

**Equipment:**

Type			corrective date
Type: Flow Line	# 4		
Comment:	3" line from wellhead to separator, line from separator to produced water, 1" line from separator to prime mover generator, 3" line from gas meter run to off location.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Telemetry, solar panels, valve pit.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		

Comment:	Gas powered.	Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.	Date:	
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		37.098944,-107.398841
Comment:	Above ground produced water tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	210 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Earth berm with liner.			
Corrective Action:				Date:

**Venting:**

Yes/No		Date:	
Comment:		Date:	
Corrective Action:		Date:	

**Flaring:**

Type		Date:	
Comment:		Date:	
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 301886 Type: WELL API Number: 007-06277 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/12/2021 Annual Brhd Completed?           

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Last reported bradenhead test: 3/3/21

08/12/2022

Corrective Action: Confirm bradenhead test has been submitted or perform annual bradenhead test per rule 419.c

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	
Waddles	Pass					
Ditches	Pass					
Compaction	Pass					
		Gravel	Pass			
Berms	Pass					

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500215	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5801423">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5801423</a>