

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2022

Submitted Date:

07/12/2022

Document Number:

702500216

FIELD INSPECTION FORM

 Loc ID 312050 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 69805
 Name of Operator: PETROX RESOURCES INC
 Address: 12600 W COLFAX AVENUE #C-440
 City: LAKEWOOD State: CO Zip: 80215
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Ryan		ryan@petrox-resources.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Duran, Alicia		alicia.duran@state.co.us	
Nystrom, Dusty	(505) 330-1328/ (719) 529-0682	nystrow@yahoo.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300115	WELL	PR	06/01/2020	GW	007-06272	MILDRED WRIGHT 1 R	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Perforated pipe within produced water secondary containment is unused equipment (IMG 03).		
Corrective Action:	Use or remove unused equipment per rule 606.	Date:	07/20/2022

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly.		
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	2" line from wellhead to separator, 2" line from separator to produced water tank, 3" line from separator to off location		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		37.106051,-107.390616

Comment: [Above ground produced water tank.](#)

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Earth berm with liner.](#)

Corrective Action:	Date:
--------------------	-------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 300115 Type: WELL API Number: 007-06272 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/12/2021 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Last reported bradenhead test: 3/3/2021

08/12/2022

Corrective Action: Confirm bradenhead test has been submitted or perform annual bradenhead test per rule 419.c

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
				Material Handling And Spill Prevention	Pass	
Compaction	Pass					
		Gravel	Pass			
Gravel	Pass					

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500217	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5801424